EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	400	(219/158).OCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 08:11
S2	374	(219/161).OCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 08:52
S3	807	(228/212).OCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 10:27
S4	432	(228/47.1).OCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 11:29
S5	128821	("219").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 11:59
S6	41803	("228").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:00
S7	29042	("269").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:00
S8	190797	("29").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:00
S9	8690	("901").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:00
S10	380213	S5 or S6 or S7 or S8 or S9	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:00
S11	4	S10 and (weld\$3 near10 (motorcycle near10 (gas or fuel) near3 tank))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:01
S12	394	S10 and (weld\$3 near10 clamp\$1 near10 (attach\$5 or engag\$6))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:02

S13	32	S10 and (weld\$3 near10 (resistance or arc or spot or seam) near10 clamp\$1 near10 (attach\$5 or engag\$6))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23
S14	40	S10 and (weld\$3 near10 (resistance or arc or spot or seam or laser) near10 (attach\$5 or engag\$6))	US PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:03
S15	117	\$10 and (weld\$3 near10 (resistance or arc or spot or seam or laser) near50 (clamp\$1 or jaw \$1 or jig\$1) near50 (attach\$5 or engag\$6))	US-PCPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:04
S16	151	S10 and (weld\$3 near10 (resistance or arc or spot or seam or laser) near50 (clamp\$1 or jaw \$1 or jig\$1) near50 (attach\$5 or engag\$6 or abut\$5))	US PCPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:04
S17	123	\$10 and (weld\$3 near5 (resistance or arc or spot or seam or laser) near20 (clamp\$1 or jaw\$1 or jig\$1) near20 (attach\$5 or engaq\$6 or abut\$5))	US POPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:04

S18	413	(weld\$3 near5 (resistance or arc or spot or seam or laser) near20 (clamp\$1 or jaw \$1 or jig\$1) near20 (attach\$5 or engag\$6 or abut\$5))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:32
S19	6	(weld\$3 near5 (resistance or arc or spot or seam or laser) near20 (clamp\$1 or jaw \$1 or jig\$1) near20 (attach\$5 or engag\$6 or abut\$5)) and ((motorcycle or vehicle or auto\$6) near10 (fuel or tank))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:33
\$20	43	(weld\$3 near5 (resistance or arc or spot or seam or laser) near20 (clamp\$1 or jaw \$1 or jg\$1) near20 (attach\$5 or engag\$6 or abut\$5) near50 spring\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/23 12:34

^{4/23/08 12:38:57} PM

C:\ Documents and Settings\ kkerns\ My Documents\ EAST\ Workspaces\ 10525124(219), wsp